

# Annexure D

## BUILDING SAFETY CERTIFICATE

No. Building safety/SA/Structural Soundness/2025,

Dated:18-11-2025

It is to certified that the existing building **CHAMPION VIDYALAYA** (name of the building or premises) at **NEAR TOWER, KADALURU VILLAGE, TADA MANDAL, TIRUPATI DISTRICT, ANDHRA PRADESH** (address) is having block(s)/Floor ( s) as per details below:

Details of Block(s) in	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
School						
No. of Floor (s) in the Block	Ground floor	NA	NA	NA	NA	NA

The building is owned/occupied by **CHAMPION VIDYALAYA**

(name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Deputy Executive Engineer, R&B Sub Division, Naidupet, Government of Andhra Pradesh**

(Name of Department/Govt.) on **18.11.2025** (date of inspection) in the presence of

**M. Ravindra Kumari, Correspondent** (name and addresses of the Manager/with effect from **18.11.2025** for a period of **two (2) years** in accordance with rule and subject to compliance of the specific conditions as appended.

1. If any further changes made to the above building the changes should be informed to this office otherwise this Certificate is Null and Void.

Issued on **18-11-2025 at 3.30 PM** by

\* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

*// Counter Signed //*

*f. m. Jeyaraj 19/11/25*  
**EXECUTIVE ENGINEER  
(R & B) DIVISION, GUDUR**

Signature with Seal : **C. Parameswari,**

Designation : **Deputy Executive Engineer**

Name & Address of Department/Office: **(R&B) Sub Division,  
Naidupet -524126**

*19/11*